

United States Steel Corporation Clairton Works 400 State Street Clainton, PA 15025

July 27, 2012

RECEIVED 2105 9 0 DUA 3AP20

Mr. Ed Peresie Department of Air Quality Bureau of Air Pollution Control 301 Thirty-Ninth Street Pittsburgh, PA 15201

U.S. Environmental Protection Agency Region III Air, Radiation & Toxics Division 1650 Arch Street Philadelphia, PA 19103-2029 ATTN: James W. Hagedorn

Mr. Steve Repler Southwest Region 400 Waterfront Drive Pittsburgh, PA 15222-4745

Department of Justice Department of Environmental Protection Environmental and Natural Resource Division Environmental Enforcement Section P.O. Box 7611 Ben Franklin Station Washington, D.C. 20044 ATTN: David Street, Esq.

Subject: USS Reference Number: 12-0265 ACHD Reference Number: N/A

"B" Battery South Igniter Flare

USS Clairton Works

## Gentlemen:

The attached form confirms our verbal report of the subject incident and satisfies the requirements of paragraph IV.8 of the Title V operating permit #0052 as issued on March 27th 2012.

I certify that based on the information and belief formed after reasonable inquiry, the statements and information in this document are true, accurate, and complete. Any questions concerning this matter should be referred to Coleen M. Davis at 412-233-1015.

Sincerely,

James F. Dudek Plant Manager Clairton Works

## NOTICE OF OUTAGE OF EQUIPMENT ARTICLE XXI - SECTION 2108.1

1. USS Reference Number: 12-0265 ACHD Reference Number: N/A

- 2. Date & Time of Breakdown: Date: 07/23/12 Time: 0625 hours
- 3. Company Name: U.S. Steel Corporation USS Clairton Works
- 4. Specific Equipment Involved or Affected: "B" Battery South Igniter Flare
- 5. BAPC Permit Number (if applicable):
- 6. Location: Clairton, PA
- 7. Nature and cause of breakdown: The South "B" Battery Igniter Flare was removed from service due to safety and clearance problems with work being performed in the near-by vicinity.
- 8. Identification of Emissions:
  - A. Type(s) (CO, NOX, SO<sub>2</sub>, Particulates, Hydrocarbons, etc.)
    No environmental impact.
  - B. Toxic qualities of each type (including its qualities as an irritant, and its potential for causing illness, disability, or mortality). N/A.
  - C. Amount of each type emitted (or likely to be emitted). N/A.
- 9. Measures taken (or to be taken) to minimize length of breakdown and amount of emissions, including shutdown or curtailment (or why it is impossible or impractical to do so). The task was completed and the Igniter Flare was available for service.
- 10. Facility back in operation Date: 07/23/12 Time: 1630 hours

Reviewed by (len) In Davis Date 7-27-/2

Senior Environmental Control Engineer Phone: 412-233-1015